







<b>Vehicle model</b>	Serie K		Serie K		C31 / C32				
<b>Year</b>	(2015>)		(2020<)		(2017>)				
<b>Engine Type</b>	DONGFENG BG 13-20 Fuel and Bi-fuel Autogas GLP (Euro 5b+)		DONG FENG DK12-06		DK 15-06 (Euro 5)				
<b>CV(kW) @ rpm</b>	82 (60) @ 5.000		84 (62) @ 5.000		115 (85) @ 5.000				
<b>N. of cylinders/cm3</b>	4 / 1.300		4 / 1.240		4 / 1.499				
<b>Volts</b>	12		12		12				
<b>Air Conditioning</b>	Only Vehicles without A/C		Only Vehicles without A/C		Only Vehicles with A/C				
<b>Recommended fittings</b>	<b>Suction</b>	<b>Discharge</b>	<b>Suction</b>	<b>Discharge</b>	<b>Suction</b>	<b>Discharge</b>			
									
<b>Compressors type</b>	TM 13 / 15 / 16 QP 13 / 15 / 16 UP-UPF 120 / 150 / 170		TM 13 QP 13		TM 13 / 15 QP 13 / 15 / UP-UPF 120 / 150 SD5H14/SD5L14				
<b>Comments</b>	- Can be fit in right hand drive vehicles		- Can be fit in right hand drive vehicles		- "E"=TM / QUE / UNICLA; - Can be fit in right hand drive vehicles - AC compressor and refrigeration compressor must not work at the same time				
<b>Clutch type</b>	Without clutch pulley		Without clutch pulley		Without clutch pulley	With clutch pulley			
	2A Ø135 4.888 rpm		8PK Ø119 3509 rpm		Poly-V 8K Ø119 3.150 rpm	Poly-V 8K Ø119 3.150 rpm			
<b>Kit No.</b>	<b>KC15120407</b>		<b>KC20080508</b>		<b>KC18010451</b>	<b>KC18010451E</b>			
<b>Last update</b>	2016-02-03		2020-09-22		2018-03-21				